



Basic measures against the spread of the CORONA virus

	Always keep a distance of at least 1.5 m during all activities, during lunch breaks, during meetings, during transport,....
	Wearing a mouth mask at the workplace is mandatory if a 1.5 m distance to bystanders cannot be maintained during work , both indoors and outdoors.
	As a mouth mask, only a surgical mouth mask, a frequently washed fabric mouth mask, an FFP2 mouth mask without exhalation valve and scarves, bandanas or buffs are NOT allowed .
	Anyone who feels ill must report this immediately to their immediate supervisor and remain at home and must follow the procedure described on https://www.info-coronavirus.be/en/quarantine-isolation/
	When you arrive at the site, use the handles at the information board at the site.
	Wash your hands thoroughly with soap and often enough. The site management provides sufficient hand soap for each washbasin!
	Cough or sneeze away from your colleagues and bystanders or into your elbow if necessary.
	Use your own work equipment and tools as much as possible. If tools are nevertheless passed on, they must first be disinfected.
	During transport to the construction site, a maximum of 2 persons per row per vehicle is allowed and a mouth mask or Plexiglas shield is mandatory for all occupants!



Basic measures against the spread of the CORONA virus

	Eat outside as much as possible or eat in shifts, maximum per 3 in the shed, at a distance of 1.5 m and not directly across each other. Clean the tables and chairs after each use, including after meetings.
	A toilet is closed and assigned to a fixed group (eg 1 per subcontractor) that is responsible for periodic cleaning itself.
	A maximum of 3 people are allowed in the dressing room at the same time.
	Meet or consult as much as possible digitally or outside at a great distance and in small groups and with a mouth mask. Wearing a mouth mask is mandatory for everyone when entering the conference chain or office chain. This is clearly displayed on the entrance door.
	When entering a windproof building, it is mandatory to wear a mouth mask and smoking is prohibited. Once at the workplace and with a distance of 1.5 m from bystanders, the mouth mask can be removed.
	The distance rules must be respected both horizontally and vertically (see scaffolding, aerial platforms, concrete works, formwork works,...).
	Personal protective equipment (PPE) is not lent and not passed on. Wearing work gloves is strongly recommended and the necessary other PPE remains mandatory depending on the risks present.
	Employees who have recently returned from zones abroad with a high risk (zones in red) must follow the procedure as described on: https://www.info-coronavirus.be/en/travels/
	The Vandenbussche site manager is the point of contact and the site corona-manager! Any determination of a suspicion of infection or disease among own employees or employees of subcontractors must be reported!